

(Reference) B14-2 drilling core photograph (1/5)



28.50m※
N34E78W

※) Fracture segment with fault gouge

(Reference) B14-2 drilling core photograph (2/5)




49.27m*




※) Fracture segment with fault gouge

(Reference) B14-2 drilling core photograph (3/5)



(Reference) B14-2 drilling core photograph (4/5)



※)断層ガウジを有する破砕部

(Reference) B14-2 Drilling core photograph (5/5)

